



GO BEYOND

ENGINEWISE

## HPT STAGE-1 BAND SEGMENT WELD REPAIR

This new weld repair developed by Pratt & Whitney for the V2500-A5/D5 HPT Stage-1 Band Segment restores surface wear and crack via welding and provides the customer an alternative to new part assembly replacement. This leads to an increase in overall yield by an estimated 90% and reduces total cost of ownership.

### SPECIFICS

P&W Engine Manual Ref: [Repair 20, VRS3725](#)

Model: [V2500 A5/D5](#)

ATA#: [72-45-23](#)

SB Ref: N/A

### AVAILABILITY

CAS has obtained OEM source approval to perform this source demonstration repair. The repair is available from 14-Sept 2018 and will be applicable for the following typical part numbers:

2A1707


2A1708

### BENEFITS


Estimated repair yield of 90%

Reduces total cost of ownership

### PART REFERENCE



MODULE 40



Component Aerospace Singapore (CAS)  
10 Loyang Lane, Singapore 508916

Ivan Wan - Aftermarket Sales Manager  
Tel: +886 2 27190395 / Mobile +886 933 923963  
Email: [ivan.wan@prattwhitney.com](mailto:ivan.wan@prattwhitney.com)