



GO BEYOND

engineWISE™

PW4000-94"/100" HPT STAGE-1 VANE NEW REPAIR- REPAIR 12 RESTORATION OF PLATFORM WALL THICKNESS

MODEL: PW4000-94"/100"
ATA#: 72-51-02
P&W ENGINE MANUAL REF: 51A357
SB REF: N/A

INTRO

The new PW4000-94"/100" HPT Stage-1 Vane repair developed by Pratt & Whitney improves overall yield and reduces customers' total cost of ownership. This new repair restores the undersize platform wall thickness via TURBOFIX®, providing an estimated 9.6% reduction in scrap rate.

AVAILABILITY

This repair is available from Oct 2019 and will be applicable for the following typical part numbers:

51K271	52K771	50K341-003
51K571	52K861	50K851-002
51K771	52K971	50K851-003
51K771-001	53K081	50K851-004
52K671	53K271	50K851-005
52K761	50K341-002	

BENEFITS

- Increase overall yield by an estimated 9.6%
- Reduces total cost of ownership
- Minimizes part scrap

A UNITED TECHNOLOGIES COMPANY

PART REFERENCE



Repair restored with
TURBOFIX®

Turbine Overhaul Services Pte Ltd
No. 5 Tuas Drive 2 Singapore 638639

Cheah Kim Wei - Repair Sales Manager

Tel: +65-6690-2745 / Mobile: +65-9699-9298
Email: kim.wei.cheah@pw.utc.com