



GO BEYOND

ENGINEWISE

PW4000-94"/100" HPT STAGE-1 VANE NEW REPAIR- REPAIR 12 RESTORATION OF PLATFORM WALL THICKNESS

The new PW4000-94"/100" HPT Stage-1 Vane repair developed by Pratt & Whitney improves overall yield and reduces customers' total cost of ownership. This new repair restores the undersize platform wall thickness via TURBOFIX®, providing an estimated 9.6% reduction in scrap rate.

SPECIFICS

P&W Engine Manual Ref: [51A357](#)

Model: [PW4000-94"/100"](#)

ATA#: [72-51-02](#)

SB Ref: N/A

AVAILABILITY

This repair is available from Oct 2019 and will be applicable for the following typical part numbers:

51K271	52K771	50K341-003
51K571	52K861	50K851-002
51K771	52K971	50K851-003
51K771-001	53K081	50K851-004
52K671	53K271	50K851-005
52K761	50K341-002	


BENEFITS

Increase overall yield by an estimated 9.6%

Reduces total cost of ownership

Minimizes part scrap

PART REFERENCE



Repair restored with TURBOFIX®

Turbine Overhaul Services Pte Ltd
No. 5 Tuas Drive 2 Singapore 638639

Cheah Kim Wei - Repair Sales Manager
Tel: +65-6690-2745 / Mobile: +65-9699-9298
Email: kim.wei.cheah@prattwhitney.com