



GO BEYOND

ENGINEWISE

HPC 12TH STAGE SEALING RING PLASMA COAT REPAIR

This new repair developed by Pratt & Whitney for the V2500-A1/A5 HPC 12th Stage Seal Ring addresses defects on the axial surface and restores serviceability on the part. By applying a plasma coat to the part (Figure 01), it increases repair yield and reduces part scrappage, leading to lower overall cost of ownership

SPECIFICS

P&W Engine Manual Ref: [Repair 064, VRS9305](#)

Model: [V2500 A1/A5](#)

ATA#: [72-41-21](#)

SB Ref: N/A

AVAILABILITY

This repair is available from 20 July 2018 and will be applicable for the following typical part numbers:

6A2506

6A5757

BENEFITS

Increases overall repair yield

Reduces cost of ownership

PART REFERENCE





Figure 1: Location of repairable surfaces

Pratt and Whitney Component Solutions Pte Ltd
61 Seletar Aerospace View, Singapore 797560

Ivan Wan - Aftermarket Sales Manager
Tel: +886 2 27190395 / Mobile: +886 933 923963
Email: ivan.wan@prattwhitney.com